About the 3D Printing Wiki

This is a 3D printing knowledge base focused on FDM printing, a documented public record of everything related to FDM 3D printing. It is hard to keep track of the range of sources on the web from video links to forum posts to models and snippets of valuable information all over the place, not to mention a place to concisely discuss code snippets, photos and graphs and whatever we need to clearly communicate the point.

We answer and ask the same questions in various forum posts and it it's hard to remember everything we did some months in the past, so this is a searchable knowledge base to point to and update as information and technology advances.



There are multiple attempts to breach the security of wikis by spambots creating registration requests. This breaks the mail loop and clutters the user base and login admin, so automated registration is disabled can only be manually done by the admins. So please contact an administrator if you feel you are eligible to request edit access. You can request edit access on the https://www.printables.com/group/creality-k1k1ck1-max-group-b5KX4vR/comments.

View the recent updates

From:
http://3dfaq.net/ - **3D Printing Wiki**

Permanent link:
http://3dfaq.net/start?rev=1716485722

Last update: **2024/05/23 17:35**