About the 3D Printing Wiki

This wiki aims to collate knowledge on printer hardware, questions about the hardware and how to resolve known issues and also CAD tools and interesting design ideas and focus on designing for 3D printing.

This is a 3D printing knowledge base focused on FDM printing, a documented public record of everything related to FDM 3D printing. It is hard to keep track of the range of sources on the web from video links to forum posts to models and snippets of valuable information all over the place, not to mention a place to concisely discuss code snippets, photos and graphs and whatever we need to clearly communicate the point.

We answer and ask the same questions in various forum posts and it it's hard to remember everything we did some months in the past, so this is a searchable knowledge base to point to and update as information and technology advances.



There are multiple attempts to breach the security of wikis by spambots creating registration requests. This breaks the mail loop and clutters the user base and login admin, so automated registration is disabled can only be manually done by the admins. So please contact an administrator if you feel you are eligible to request edit access. You can request edit access on the Creality K1 forum on printables.

There are two ways to navigate around:

- Following the menus to the left from the top down to the bottom
- Using the search bar above and typing in what you are looking for.

View the recent updates

From:
http://3dfaq.net/ - **3D Printing Wiki**

Permanent link:
http://3dfaq.net/start?rev=1748180752

Last update: **2025/05/25 13:45**